

MODEL
172211 Contact Actuation
172212 Toenail–Single Sequential Actuation
172213 Single Sequential Actuation



<p>HB0164</p> <p>KB4136</p> <p>KB4137</p>	<p>HB0236</p> <p>KB4136</p> <p>KB4137</p>
<p>Contact Actuation Single Sequential Actuation</p>	<p>Toenail–Single Sequential Actuation</p>

SN70 NAILER

REPLACEMENT PARTS CHART

LISTA DE PARTES DE REPUESTO • ERSATSTEILE-LISTE • LISTE DE PIÈCES DE RECHANGE

<u>PART NO.</u>	<u>DESCRIPTION</u>	<u>DESCRIPCIÓN</u>	<u>BESCHREIBUNG</u>	<u>DÉSIGNATION</u>
FC0243	PLATE	PLACA	PLATTE	PLAQUE
GC0576	RAIL	CARRIL	SCHIENE	RAIL
HB0164	SAFETY YOKE	SEGURO	AUSLÖSESICHERUNG	PALPEUR DE SÉCURITÉ
HB0236	SAFETY YOKE	SEGURO	AUSLÖSESICHERUNG	PALPEUR DE SÉCURITÉ
KB4136	SPRING	RESORTE	FEDER	RESSORT
KB4137	SPRING	RESORTE	FEDER	RESSORT